

Diagnostic Report for Kettle Falls West (0KFRW:KFRW001)

Report: Kettle Falls International Railway

Time: Mon Mar 6 14:04:30 2006 EST

Site Information

Cars In/Out: 0 in, 0 out

Trains In/Out: 0 in, 0 out

Total Car Moves: 53 cars

Last Maintenance Message: 2006-03-06 10:57:00

Current Weather: 37 , Mostly Cloudy

Percent Tagged Locomotives: 80%

Percent Tagged Cars: 98.1132075471698%

Percent Messages Dispatched: 100%

Last Train Headers:

time	dir	min	max	mov	l con	l count	l tag	c con	c count	c tag
2006-03-06 10:16:00	N	18	23	A	G	5	4	G	53	52
2006-03-04 18:00:00	S	13	23	A	G	4	4	G	37	36
2006-03-04 10:35:00	N	24	27	A	G	4	4	G	27	27
2006-03-03 18:42:00	S	17	22	A	G	4	4	G	23	23
2006-03-03 09:40:00	N	12	17	A	G	4	4	G	43	42

C8: Antenna 6

Alert Status: Pending failure, non-critical

Potential Failure: One of the antennas is not functioning properly.

Report: AEI Site #0KFRW:KFRW001 Kettle Falls West, antenna performance degradation indicated as handshake count for one antenna < 25% of total handshakes.

Details:

antenna0	antenna1	line items
1364	1884	53